

# What kind of oil does the photovoltaic bracket factory need

### What is solar photovoltaic bracket?

Solar photovoltaic bracket is a special bracket designed for placing, installing and fixing solar panels in solar photovoltaic power generation systems. The general materials are aluminum alloy, carbon steel and stainless steel. The related products of the solar support system are made of carbon steel and stainless steel.

## What types of solar photovoltaic brackets are used in China?

At present, the solar photovoltaic brackets commonly used in China are divided into three types: concrete brackets, steel brackets and aluminum alloy brackets. Concrete supports are mainly used in large-scale photovoltaic power stations. Because of their self-weight, they can only be placed in the field and in areas with good foundations.

#### What materials are used in solar support system?

The general materials are aluminum alloy, carbon steel and stainless steel. The related products of the solar support system are made of carbon steel and stainless steel. The surface of the carbon steel is hot-dip galvanized and will not rust for 30 years in outdoor use.

#### What materials are used in solar stents?

Highly wear-resistant materials are used in the solution to resist wind and snow loads and other corrosive effects. Comprehensive use of aluminum alloy anodic oxidation,ultra-thick hot-dip galvanizing, stainless steel, anti-UV aging and other technical processes to ensure the service life of solar stents and solar tracking.

Boyue Photovoltaic Technology Co., Ltd is located in Hebei Province, China, the factory covers an area of 18,000 square meters, and 150 workers, 66 kilometers away from Beijing Airport and 180 kilometers away from Tianjin Xingang.Our ...



# What kind of oil does the photovoltaic bracket factory need

Contact us for free full report

Web: https://publishers-right.eu/contact-us/ Email: energystorage2000@gmail.com

WhatsApp: 8613816583346

